

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA 8, CALIF.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080197-6

N^o128170

RECEIVED FROM

DATE REC'D 1-21-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO

CONTRACT
CODE NO.DRAWING
NUMBERDWG. DASH OR
STANDARD PART NO.DWG.
REV.LOT
NO.CLASS
NUMBEROPER.
NUMBERBUY OUT
CODE NO.

O

ACCT. OR
V.O. NO.

S.O. NO.

QUANTITY
RECEIVED

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED

REJECTED

REMARKS

SHIP MEMO. 85867

RECEIVED
BYINSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA 8, CALIF.

N^o128174

RECEIVED FROM

DATE REC'D 1-21-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO

CONTRACT
CODE NO.DRAWING
NUMBERDWG. DASH OR
STANDARD PART NO.DWG.
REV.LOT
NO.CLASS
NUMBEROPER.
NUMBERBUY OUT
CODE NO.

O

ACCT. OR
W.O. NO.

S.O. NO.

QUANTITY
RECEIVED

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED

REJECTED

REMARKS

10

730163-085 CONDUCTOR GROUND AN 3102-1 28-71P

SHIP MEMO. 85864

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080197-6

RECEIVED
BYINSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.